

CERCELL A/S
Nørrelundvej 10
2730 Herlev
Denmark

Processing Facility Denmark E-Beam
Sales Order # 2788812
P.O.# 1901
Processing Start 11/6/2021 03:54:39 GMT
Processing End 11/6/2021 04:40:27 GMT

Work Order # 2901013			Customer Requested Target Dose	4 x 8 kGy - 4 sides	
Qty	UOM	Item Number	Item Description	Customer Lot Number	Customer Load Number
18	CR	CC_CAD12C	CAD12	97	1
8	CR	CC_CAD12C	CAD12	97	2
1	CR	CC_CAD21-1	CAD21	97	2
27	CR	Total			

Quality Test Summary

Op#	Quality Test Description	Minimum Spec	Maximum Spec	Result
650.00	Reference Minimum Dose	7.2 kGy	8.8 kGy	7.9 KGY
650.00	Reference Maximum Dose	7.2 kGy	8.8 kGy	8.0 KGY

Sterigenics certifies that the materials listed above (as described by the Manufacturer) received the indicated doses within the precision and accuracy of the dosimetry system employed.

All boxes including the ones with item number CC_Merck13L have been flipped and irradiated from all 4 sides with a target dose of 8.0kGy each time, to an accumulated target dose of 32kGy.

See Damage Report 226318

Certified By:

Louise A. De

Date:

11 Jun 2021

R553721
Version STER0001

Sterigenics
Damage Report

11/06/21 5:23:37 GM
Page - 1

Customer: 118180
CERCELL A/S
Nørrelundvej 10
2730 Herlev
Denmark

Damage Report ID: 226318

SO: 2788812
WO: 2901013
PO: 1901
Item Number: CCL_CC_CAD12C
CC_CAD12C
CAD12

Customer Load Number: 1
Customer Lot Number: 97

Pallet ID: 65768253
Quantity Damaged: 1 CR Carton
Severity: Minor
Notify Customer: Yes
Damage Category: By Sterigenics
Damage Found: Chamber
Location of Damage: Side of Case
Damage Type: Hole
Damage Caused: Equipment or Facility

Comments:

Damage Reported By: MSKOVGAARD

Date: 11/06/21

Customer Notified By:

MS

Date:

11 JUNI 2021

Bestrales og retur på pallen.

MS
11 JUNI 2021

Skovgaard, Martin

From: Flemming Petersen <flemming.petersen@cercell.com>
Sent: Friday, June 11, 2021 7:46 AM
To: Skovgaard, Martin
Cc: 68_CustService
Subject: [EXTERNAL] Sv: Sterigenics LOT 97

CAUTION: This email originated from outside of the organization. **DO NOT CLICK** links or attachments unless you recognize the sender and know the content is safe.

Hej Martin

Ja, det er jo hvad der kan ske.

Hvornår kan vi afhente kasserne?

Best regards/Med venlig hilsen
Flemming Petersen



CerCell A/S

Nørrelundvej 10 // DK-2730 Herlev // Denmark

Phone +45 4411 5400 // Mobile +45 42 444 000 // Mail flemming.petersen@cercell.com

Company reg. No. DK31940346 // www.cercell.com



Fra: Skovgaard, Martin <MSkovgaard@eu.sterigenics.com>
Sendt: 11. juni 2021 07:30
Til: Flemming Petersen <flemming.petersen@cercell.com>
Cc: 68_CustService <68_CustService@eu.sterigenics.com>
Emne: RE: Sterigenics LOT 97

Hej Flemming,

Vi er desværre kommet til at lave et hul i en af jeres kasser.

Kassen er bestrålet.

Se Damage Report samt foto.

From: Flemming Petersen <flemming.petersen@cercell.com>
Sent: Friday, June 4, 2021 10:51 AM
To: 68_CustService <68_CustService@eu.sterigenics.com>
Subject: [EXTERNAL] Sterigenics LOT 97

MS 11 JUNI 2021
SO: 2788812

CAUTION: This email originated from outside of the organization. **DO NOT CLICK** links or attachments unless you recognize the sender and know the content is safe.

Best regards/Med venlig hilsen
Flemming Petersen




CerCell A/S

Nørrelundvej 10 // DK-2730 Herlev // Denmark

Phone +45 4411 5400 // Mobile +45 42 444 000 // Mail flemming.petersen@cercell.com

Company reg. No. DK31940346 // www.cercell.com



This e-mail and any files transmitted with it may contain privileged and/or confidential information. If you believe this e-mail or any of its attachments were not intended for you, you must not use, distribute, forward, print or copy this e-mail or any attached files. If you have received this e-mail in error, please notify the sender by reply e-mail and then immediately delete the email and all attachments.